Map ID MAP FINDINGS

Direction Distance

Elevation Site Database(s) EPA ID Number

 1165
 MANHOLE #30800
 NY Spills
 S106014536

 West
 HIGHLAND AV & NEPTUNE AV
 N/A

> 1 BROOKLYN, NY

1.538 mi. 8123 ft.

Relative: SPILLS:
Higher Name: MANHOLE #30800

Actual: Address: HIGHLAND AV & NEPTUNE AV

0 ft. City,State,Zip: BROOKLYN, NY Spill Number/Closed Date: 0302189 / 2006-10-23

 Facility ID:
 0302189

 Facility Type:
 ER

 DER Facility ID:
 169227

 Site ID:
 203493

 DEC Region:
 2

Spill Cause: Equipment Failure

 Spill Class:
 C4

 SWIS:
 2401

 Spill Date:
 2003-06-01

 Investigator:
 JHOCONNE

 Referred To:
 Not reported

 Reported to Dept:
 2003-06-01

 CID:
 390

Water Affected: Not reported Commercial/Industrial Spill Source: Spill Notifier: Responsible Party Cleanup Ceased: Not reported Cleanup Meets Std: False Last Inspection: Not reported Recommended Penalty: False **UST Trust:** False Remediation Phase: 0

Date Entered In Computer: 2003-06-01
Spill Record Last Update: 2006-10-23
Spiller Name: CALLER
Spiller Company: CON ED

Spiller Address: 4 IRVING PLACE

Spiller Company: 001

Contact Name: LARRY COSTA

DEC Memo: "10/23/06 - See e-docs for Con Ed report detailing cleanup and closure. Prior to Sept, 2004 data translation this spill Lead DEC

Field was RODRIGUEZ E2MIS 148546 6/1/03 0900HRS HENRIGUEZ #48257 #9
REPORTS FOUND APPROX 3-GALLONS OF DIFLECTRIC FLUID THATS LEAKING FR

REPORTS FOUND APPROX 3-GALLONS OF DIELECTRIC FLUID THATS LEAKING FROM 4KV SWITCH FEEDER 3136 , ONTO 300 GALLONS OF WATER IN MH-30800. IT

APPEARS TO BE CONTAINED AT THIS TIME NO SEWERS OR WATERWAYS EFFECTED. THERE IS STEAM & SMOKE FROM SWICTH.NO PRIVATE PROPERTY INVOLVED.

1-SAMPLE TAKEN ENVIR TAG 39100 PLACED. SHIFT MGR.KENNY STECK REPORTS WORK WILL NOT BE COMPLETED WITHIN 24HRS. INCIDENT WILL NOT BE PUT ON 24HR DEC PROGRAM. CLEANUP PENDING TEST RESULT. 6/1/03-1021HRS CIG

L.COSTA NOTIFIED UPDATE********************** 06-01-03 02:21HRS LAB

SEQ# 03-04547-001 3PPM. S.PACE 49874.

COMPLETED. S.PACE 49874. UPDATE****************** 19:40HRS CIG WAS NOTIFIED OF DIRT SUMP. Update - 6/2/03 @ 0600 hrs - Updated event involved materials and event involved persons lists. UPDATE 6/3/03

PER FDR REP THE SWITCH WAS REPAIRED "

EDR ID Number

Map ID MAP FINDINGS
Direction

Distance Elevation Site

EDR ID Number
te Database(s) EPA ID Number

Remarks: "3 gals spilled - was smoke from a swithch - clean up is pending the

power being turned off con ed #148546 - con ed called back 19:48 stating clean up was complete and eathen sump was discovered in

manhole"

All Materials:

Site ID: 203493 Operable Unit ID: 870050 Operable Unit: 01 Material ID: 571417 Material Code: 0541A Material Name: dielectric fluid Case No.: Not reported Petroleum Material FA: Quantity: 3.00 Units: G Recovered: .00

Oxygenate: Not reported